



Note:

1. Treat all cut edges with Holdfast® Metalex® Clear
2. 50 mm strip of neutral cure silicon sealant must be provided at termination points of all Z flashings at meter boxes

SC034B: Shadowclad® Meterbox Horizontal Cross Section (Cavity)