



- Note:
1. Treat all cut edges with Holdfast® Metalex® Clear

SC014: Shadowclad® Vertical Joint with Top Hat Flashing (Cavity)